

VEHICLE INSPECTION REPORT

PO13DYY

Daf LF 45.140

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 01/04/2013

VIN XLRAE45FF0L425122

Axle Combi 4x2

Year 2013

Body Style Box Van

Rear Suspension Steel

Mileage 884,932 Km Warranted

MOT Due 30/09/2025

Tail Lift Cantilever

Fuel Type Diesel

Cab Type DAY CAB

Colour RED

Gearbox MANUAL

COLLECTED AS NON RUNNER - CORROSION

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features

- Cruise control
- Radio/CD
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Dented
With Paint Damage



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door Pad osf
Soiled
Heavy



5: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition		OK	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK			