

VEHICLE INSPECTION REPORT

PJ69XKD

Daf XF 480

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	23/01/2020	Body Style	Tractor Unit	Gearbox	AUTOMATIC
Year	2020	MOT Due	Expired	Axle Combi	6x2
Mileage	606,297 Km Warranted	CAP Clean	£10,050.00	Steering Combi	Mid-Lift Steer
Fuel Type	Diesel	CAP Average	£9,600.00	Rear Suspension	Air
Colour	WHITE	CAP Below	£8,850.00		
VIN	XLRTGH4300G285815	Cab Type	SPACE CAB		

WARNING LIGHTS ON DASH, DASH PARTS MISSING

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Park assist camera
- Auxiliary input socket
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Thru Paint



2: Bonnet
Chipped
Multiple Chips



3: Panel Front
Scratched
Over 25mm Thru Paint



4: Door Moulding nsf
Scratched (Painted)
Over 25mm Thru Paint



5: Wing nsf
Scratched
Over 25mm Thru Paint



6: Panel Rear
Dented
With Paint Damage



7: Qtr Panel Trim ns
Broken
Replace



8: Qtr Panel Trim os
Broken
Replace



9: Screen Front
Chipped
UpTo 10mm



10: Carpets Front
Missing
Replace



11: Fascia Panel
Missing
Replace



12: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK