

VEHICLE INSPECTION REPORT

MK73GPY

Maxus Deliver 9 2.0 D20 150PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 04/10/2023

Year 2023

Mileage 28,180 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN LSH14J7C2PA119722

Body Style Panel Van

MOT Due 03/10/2026

CAP Clean £9,800.00

CAP Average £9,225.00

CAP Below £8,125.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag


Photos







Condition Check



Damage Photos



1: Panel Front
Chipped
Multiple Chips



2: Door Mirror Assy nsf
Broken
Replace



3: Qtr Panel nsr
Dented
With Paint Damage

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		