

# VEHICLE INSPECTION REPORT

**MK73GNV**

## Maxus Deliver 9 2.0 D20 150PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 13/10/2023

Year 2023

Mileage 22,588 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN LSH14J7C0PA119833

Body Style Panel Van

MOT Due 12/10/2026

CAP Clean £10,050.00

CAP Average £9,500.00

CAP Below £8,350.00

Gearbox MANUAL

Gears 6

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS

### Tyres

NSF

NSR

OSF

OSR

Spare


## Features

- Bluetooth connection
- Digital radio
- Passenger airbag
- Cruise control
- Air conditioning
- Central locking
- Rear parking sensor
- Front electric windows
- Cloth seat trim
- Auxiliary input socket
- Drivers airbag

## Photos










## Condition Check



## Damage Photos



1: Wing of  
Scratched  
Over 25mm Not Thru Paint



2: Bumper Front  
Scratched  
25 to 100mm Thru Paint





3: Sill ns  
Dented  
With Paint Damage



4: Sill ns  
Dented  
Over 30mm

**Interior**

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	OK	<b>Odour</b>	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		