

VEHICLE INSPECTION REPORT

BX58JL

Ford Transit T350 2.4 TDCI 115PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 10/01/2009

Fuel Type Diesel

Body Style Access Platform

Year 2009

Colour WHITE

Gearbox MANUAL

Mileage 229,091 Km Warranted

VIN WF0XXXBDFX8L28084

Gears 6

WARNING LIGHT ON DASH 3850KG GVW, SIDE LOAD DOOR

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


Features

- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Cracked
Over 25mm



3: Bumper Front
Scratched
Over 100mm Thru Paint



4: Wing nsf
Rusted
Over 5mm



5: Qtr Panel nsr
Poor Previous Repair
Rippled UpTo 30%



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: C Post os
Dented
Over 30mm



8: Qtr Panel osr
Dented
Over 30mm



9: Wing osf
Rusted
Over 5mm



10: Wing osf
Dented
Over 30mm



11: Door Pad osf
Scuffed
Over 25mm



12: Carpets Front
Holed
Over 3mm



13: Seat Base Cover osf
Torn
Over 3mm



14: Fascia Panel
Holed
Over 3mm



15: Seat Base Cover nsf
Soiled
Heavy

16: Dash Warning Lights
Displayed
No Action

Interior

Carpet Condition		Poor	Upholstery Condition		Poor
Seat Condition		Poor	Odour		-
Engine Runs		OK	No Excessive Smoking		OK
EML light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		Fault	Service indicator light illuminated		Fault