

VEHICLE INSPECTION REPORT

PJ69XEM

Daf LF 260

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

| | | | | | |
|-----------|----------------------|-------------|------------|-----------------|-----------|
| Reg. date | 13/01/2020 | Body Style | Fridge Box | Gearbox | AUTOMATIC |
| Year | 2020 | MOT Due | Expired | Axle Combi | 4x2 |
| Mileage | 350,610 Km Warranted | CAP Clean | £17,950.00 | Rear Suspension | Air |
| Fuel Type | Diesel | CAP Average | £17,150.00 | Rear Doors | Barn </td |
| Colour | WHITE | CAP Below | £14,400.00 | Tail Lift | Tuckaway |
| VIN | XLRAEL3700L491837 | Cab Type | DAY CAB | | |

COLLECTED AS NON RUNNER - POOR STARTER, FRIDGE CONTROLS INOP, WARNING LIGHT ON DASH CARRIER SUPRA 1150MT UNIT, STANDBY PLUG, TWIN EVAPS, SEPERATER PANELS,

Tyres



| | | | | |
|-------|------|------|------|------|
| NSF | NSI1 | NSI2 | NSI3 | NSI4 |
| OSF | OSI1 | OSI2 | OSI3 | OSI4 |
| Spare | NSO1 | NSO2 | NSO3 | NSO4 |
| | OSO1 | OSO2 | OSO3 | OSO4 |

Features

- Bluetooth connection
- Cruise control
- Digital radio
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Number Plate Front
Broken
Replace



2: Bonnet
Chipped
Multiple Chips



3: Bumper Front Grill
Broken
Replace



4: Bumper Front
Cracked
Over 25mm



5: Panel Front
Hole
Over 10mm



6: Panel Front
Scratched
Over 25mm Thru Paint



7: Qtr Panel Trim ns
Broken
Replace




8: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



9: Qtr Panel nsr
Dented
With Paint Damage



10: Door osr
Cracked
Replace



11: Qtr Panel osr
Scratched
Over 25mm Thru Paint



12: Qtr Panel osr
Scratched
Over 25mm Thru Paint



13: Qtr Panel osr
Cracked
Replace



14: Door osf
Scratched
Over 25mm Thru Paint



15: Door osf
Dented
With Paint Damage



16: Seat Base Cover osf
Torn
Over 3mm



17: Dash Warning Lights
Displayed
No Action

Interior

| | | | |
|-------------------------|-------|-----------------------------|----|
| Carpet Condition | OK | Upholstery Condition | OK |
| Seat Condition | Poor | Odour | - |
| Engine Runs | Fault | No Excessive Smoking | OK |
| EML light illuminated | Fault | DPF light illuminated | OK |
| ABS light illuminated | OK | | |