

VEHICLE INSPECTION REPORT

EU67WWV

Scania P 410

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 01/11/2017

Year 2017

Mileage 371,755 Km Not Warranted

Fuel Type Diesel

Colour WHITE

VIN YS2P8X40005481115

Body Style Tipper

MOT Due 31/08/2025

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 8x4

Rear Suspension Steel

WARNING LIGHT ON DASH BOWELD 3 WAY STEEL BODY, EDBRO TIPPING GEAR, SHEETING SYSTEM

Tyres

NSF NSI1

NSI2

NSI3

NSI4

OSF OSI1

OSI2

OSI3

OSI4

Spare NSO1

NSO2

NSO3

NSO4

OSO1

OSO2

OSO3

OSO4

Features

- Bluetooth connection
- Auxiliary input socket
- Central locking
- Cruise control
- Radio/CD
- Cloth seat trim
- Navigation system
- Air conditioning
- Park assist camera
- Front electric windows


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Chipped
Multiple Chips



3: Bumper Front
 Scratched
 Over 100mm Thru Paint



4: Door osf
 Scratched
 Over 25mm Thru Paint



5: Bumper Front
 Scratched
 Over 100mm Thru Paint



6: Screen Front
 Cracked
 Replace

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		