

VEHICLE INSPECTION REPORT

DN71HYH

BMW X3 xDrive 30e M Sport

Inspection

Serious Damage? No

Vehicle

VAT Margin

V5 Present

nama
GRADE
2

Details

Reg. date 30/11/2021

Year 2021

Mileage 42,662 Miles Not Warranted

Fuel Type Hybrid Electric

Colour BLACK

VIN WBA62DP0609J97802

Body Style SUV

Keys 2

MOT Due 19/02/2026

CAP Clean £27,850.00

CAP Average £26,550.00

CAP Below £25,200.00

Gearbox AUTOMATIC

Gears 8

Axle Combi 4x4

Rear Suspension Steel

NO CHARGING CABLES HEATED STEERING WHEEL

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Navigation system
- Reverse parking aid
- USB/iPod interface
- Roof rails
- Front electric windows
- Sports seats
- 3x3 point rear seat belts
- Tyre pressure monitor
- Leather seat trim
- Cruise control
- Park assist camera
- Service indicator
- Body coloured bumpers
- Air conditioning
- Rear armrest
- Steering wheel rake adjustment
- ABS
- Alarm
- Alloy wheels
- Front parking sensor
- Rear parking sensor
- Trip computer
- Electric door mirrors
- Climate control
- Rear electric windows
- Steering wheel reach adjustment
- Drivers airbag
- Central locking
- Heated front seat
- Rear wiper
- Radio/CD
- Front fog lights
- Electrically adjustable drivers seat
- Rear headrests
- Metallic Paint
- Passenger airbag
- Remote central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Rear
Scratched
25 to 100mm Thru Paint



3: Door osr
 Scratched
 Over 25mm Not Thru Paint

Interior

| | | | |
|--------------------------|----|--|----|
| Carpet Condition | OK | Upholstery Condition | OK |
| Seat Condition | OK | Odour | - |
| Engine Runs | OK | Gearbox 1st and Reverse Test | OK |
| Brakes | OK | Clutch Slip Test from Static | OK |
| Turbo Boosting | OK | Gearbox Static Gear Selection (engine running) | OK |
| | | No Excessive Smoking | OK |
| EML light illuminated | OK | Oil warning light illuminated | OK |
| Airbag light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | Service indicator light illuminated | OK |
| Roof / sunroof | OK | Radio | OK |
| Windows | OK | Steering | OK |
| Sat nav | OK | | |