

VEHICLE INSPECTION REPORT

C314920

CARTWRIGHT CURTAINSIDE

Inspection

Vehicle

| | |
|-----|----------|
| VAT | Plus VAT |
| V5 | N/A |

Details

| | | | | | |
|-----------|------------|------------|------------|-----------------|------|
| Reg. date | 01/09/2011 | Colour | BLUE | Brakes | Drum |
| Year | 2011 | VIN | 110693 | Axle Combi | Tri |
| Mileage | TBC | Body Style | Trailer | Rear Suspension | Air |
| Fuel Type | | MOT Due | 31/08/2026 | Rear Doors | Barn |

BPW AXLES, RAISE & LOWER VALVE, ENXL RATED CURTAINS

Tyres

| |
|-------|
| NSF |
| NSR |
| OSF |
| OSR |
| Spare |

Photos



