



COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE

01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

PE63NCN

DAF LF 45.140

Inspection

Vehicle

VAT	Plus VAT
V5	Present

Details


Reg. date	25/10/2013	VIN	XLRAE45FF0L431828	Gearbox	MANUAL
Year	2013	Body Style	Box Van	Axle Combi	4x2
Mileage	945,133 Km Warranted	Service history	Yes	Rear Suspension	Steel
Fuel Type	Diesel	MOT Due	31/05/2026	Tail Lift	Cantilever
Colour	RED	Cab Type	DAY CAB		



COLLECTED AS NON-RUNNER, CORROSION/GEARBOX/CLUTCH REQUIRE ATTN *WARNING LIGHT ON DASH* *TAIL LIFT IN-OP*

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Photos





Condition Check



Damage Photos



1: Wing of
Cracked
Replace

2: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



3: Bonnet
Poor Previous Repair
Poor Paint

4: Grille Front
Broken
Replace



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

6: Bumper Front Moulding
Scratched (Painted)
Over 25mm Thru Paint



7: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm

8: Wing Front Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



9: Door nsf
Scratched
Over 25mm Not Thru Paint

10: Qtr Panel osr
Scratched
Over 25mm Thru Paint



11: Fuel Flap
Missing
Replace

12: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



13: Qtr Panel osr
Scratched
Over 25mm Thru Paint

14: Door osf
Scratched
Over 25mm Not Thru Paint



15: Handle Outer osf
Broken
Replace

16: Door Mirror Assy osf
Scuffed (Unpainted)
Over 100mm



17: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK