

VEHICLE INSPECTION REPORT

M500KTL

SCANIA R143.450 TOPLINE STREAMLINE

| lmr | orted |
|-------|---------|
| 11111 | JUI LEU |
| | |

Inspection Vehicle

| VAT | Margin | |
|-----|----------------|--|
| V5 | Buyer To Apply | |

Details

| Reg. date | 01/07/2017 | Colour | MULTI-COLOURED | Gearbox | MANUAL | |
|-----------|----------------------------|------------|-------------------|------------|--------|--|
| Year | 1995 | VIN | VLURA4X2A09007150 | Axle Combi | 4x2 | |
| Mileage | 25,897 Km Not Warranted | Body Style | Tractor Unit | | | |
| | | Cab Type | TOPLINE CAB | | | |
| Fuel Type | Diesel | | | | | |

LEFT HAND DRIVE, ROYAL CLASS CUSTOM INTERIOR, TRUCKMAX EXHAUST SYSTEM, TOOLBOXES IN SIDE LOCKERS, RIGHT TURN CAMERA, SIGHN WRITING IS STICKERS, 'THE ITALIAN JOB' CUSTOM AIR BRUSHING, ORIGINALLY FROM ITALY

| Tyres | | | |
|--------------|--|---|--|
| Tyres NSF | | | |
| NSR | | | |
| OSF | | · | |
| OSR | | | |

Features

Air conditioning

Photos

Spare















