

VEHICLE INSPECTION REPORT

YJ17FGV

Peugeot Boxer 435 2.0 BLUE HDI 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 06/06/2017

Year 2017

Mileage 99,090 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3YD2MFC12D11570

Body Style Ambulance

MOT Due 29/11/2025

CAP Clean £5,125.00

CAP Average £4,325.00

CAP Below £3,275.00

Gearbox MANUAL

Gears 6

AD BLUE, SIDE LOADING DOOR, E/MIRRORS, FERGO PEGASUS STRETCHER (YEAR 2017)

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Navigation system
- Park assist camera
- Rear parking sensor
- Air conditioning
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Screen Front
Chipped
UpTo 10mm



3: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



4: Door Mirror Assy nsf
Broken
Replace



5: Qtr Panel nsr
Dented
Between 10mm + 30mm



6: Qtr Panel Arch Extension ns
Scuffed (Unpainted)
UpTo 100mm



7: Steering Wheel
Damaged
Replace



8: Other
N/A
N/A

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK