

## VEHICLE INSPECTION REPORT

**YJ17FHE**

### Peugeot Boxer 435 2.0 BLUE HDI 130PS

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 To Follow

#### Details

Reg. date 05/06/2017

Year 2017

Mileage 139,545 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN VF3YD2MFC12D17674

Body Style Ambulance

MOT Due 12/05/2026

CAP Clean £4,075.00

CAP Average £3,450.00

CAP Below £2,600.00

Gearbox MANUAL

Gears 6

\*WARNING LIGHT ON DASH\* AD BLUE, SIDE LOADING DOOR, E/MIRRORS, FERGO PEGASUS STRETCHER (YEAR 2017)

#### Tyres

NSF

NSR

OSF

OSR

Spare


### Features

- Navigation system
- Front electric windows
- Park assist camera
- Central locking
- Rear parking sensor
- Air conditioning


### Photos







## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Missing  
Replace



2: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm





3: Bonnet  
Chipped  
Multiple Chips



4: Screen Front  
Chipped  
Over 10mm



5: Bumper Front Moulding  
Scuffed (Unpainted)  
UpTo 100mm



6: Door Mirror Assy nsf  
Scuffed (Unpainted)  
UpTo 100mm



7: Other  
N/A  
N/A



8: Qtr Panel Moulding os  
Scuffed (Unpainted)  
UpTo 100mm



9: Qtr Panel osr  
Dented  
With Paint Damage

Interior

Carpet Condition		Upholstery Condition	
Seat Condition	Average	Odour	Average
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	Fault	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK