

VEHICLE INSPECTION REPORT

YP69NRK

Citroen Berlingo 650 1.6 BLUE HDI 75PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 06/11/2019

Year 2019

Mileage 102,995 Miles Not Warranted

Fuel Type DIESEL

Colour WHITE

VIN VR7EFBHWBKJ608976

Body Style Panel Van SWB

MOT Due 05/11/2025

CAP Clean £4,375.00

CAP Average £3,850.00

CAP Below £3,075.00

Gearbox MANUAL

Gears 5

AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF


OSR


Spare

Features


- Front parking sensor
- Rear parking sensor
- Air conditioning
- Front electric windows

Photos







Condition Check



Damage Photos



1: A Post ns
Scratched
Over 25mm Thru Paint



2: Panel Rear
Scratched
UpTo 25mm Thru Paint

Interior

Carpet Condition OK
Seat Condition OK

Upholstery Condition OK
Odour No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK