

VEHICLE INSPECTION REPORT

DS69SUY

Vauxhall Vivaro 2900 1.5 100PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 26/11/2019

Year 2019

Mileage 111,916 Miles Not Warranted

Fuel Type DIESEL

Colour WHITE

VIN VXEVBYHRKL7009147

Body Style Panel Van L2

MOT Due 01/01/2026

CAP Clean £5,000.00

CAP Average £4,400.00

CAP Below £3,525.00

Gearbox MANUAL

Gears 6

AD BLUE, TWIN LOADING DOORS, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Rear parking sensor
- Air conditioning
- Front electric windows
- Leather seat trim

Photos






Condition Check



Damage Photos



1: Door osf
Scratched
UpTo 25mm Thru Paint

Interior

Carpets Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Turbo Boosting	OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK	No Excessive Smoking	OK