

VEHICLE INSPECTION REPORT

Vehicle

DG66UWR

Man TGS 26.360

Inspection

Serious Damage? No VAT Plus VAT V5 To Follow Details Reg. date 13/01/2017 VIN WMA18SZZ4HM721343 Axle Combi 6x2 Year 2017 Body Style Curtainside Rear Suspension Air Mileage 433,521 Km Warranted MOT Due 31/12/2025 Rear Doors Barn Fuel Type Diesel Cab Type DAY CAB Colour BLUE Gearbox MANUAL						
Details Reg. date 13/01/2017 VIN WMA18SZZ4HM721343 Axle Combi 6x2 Year 2017 Body Style Curtainside Rear Suspension Air Mileage 433,521 Km Warranted MOT Due 31/12/2025 Rear Doors Barn Fuel Type Diesel Cab Type DAY CAB	Serious Damage?	No	VAT	Plus VAT		
Reg. date 13/01/2017 VIN WMA18SZZ4HM721343 Axle Combi 6x2 Year 2017 Body Style Curtainside Rear Suspension Air Mileage 433,521 Km Warranted MOT Due 31/12/2025 Rear Doors Barn Fuel Type Diesel Cab Type DAY CAB			V5	To Follow		
Year2017Body StyleCurtainsideRear SuspensionAirMileage433,521 Km WarrantedMOT Due31/12/2025Rear DoorsBarnFuel TypeDieselCab TypeDAY CAB	Details					
Mileage433,521 Km WarrantedMOT Due31/12/2025Rear DoorsBarnFuel TypeDieselCab TypeDAY CAB	Reg. date	13/01/2017	VIN	WMA18SZZ4HM721343	Axle Combi	6x2
Fuel Type Diesel Cab Type DAY CAB	Year	2017	Body Style	Curtainside	Rear Suspension	Air
	Mileage	433,521 Km Warranted	MOT Due	31/12/2025	Rear Doors	Barn
Colour BLUE Gearbox MANUAL	Fuel Type	Diesel	Cab Type	DAY CAB		
	Colour	BLUE	Gearbox	MANUAL		

MOT HISTORY INCORRECTLY RECORDED IN MILES/KM MOFFET BRACKETS, SERVICE SCHEDULE LIST AVAILABLE, REAR LIFT

Tyres

NSF	NSI1	NSI2	NSI3	NSI4	
OSF	OSI1	OSI2	OSI3	OSI4	_
Spare	NSO1	NSO2	NSO3	NSO4	
	OSO1	OSO2	OSO3	OSO4	

Features

- Cruise control
 Central locking
- Park assist cameraCloth seat trim
- Radio/CD

Front electric windows

Photos



















Condition Check



Damage Photos



1: Door Pad osf Broken Replace

Interior

Carpet Condition	OK	Upholstery Condition Poor	
Seat Condition	OK	Odour -	
Engine Runs		OK No Excessive Smoking	OK

EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		