

VEHICLE INSPECTION REPORT

A162353

Volvo B9R PLAXTON PANTHER

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	Colour	Gearbox	AUTOMATIC
Year	VIN	Axle Combi	4x2
Mileage 197,891 Km Not Warranted	Body Style Coach	Rear Suspension	Air
Fuel Type	Cab Type DAY CAB		

*5% BUYERS FEE,**NOT FOR AUCTION** FOR TENDER ON FRIDAY 3RD OCTOBER* 53 SEATS + DRIVER KNEEL FUNCTION, RECLINING LEATHER SEATS, 3 PT SEAT BELTS, FOOT REST, OVERHEAD STOWAGE, REAR EMERGENCY EXIT, FULL WIDTH UNDERBODY STORAGE *MOD 654 FROM T/F*

Tyres



NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Bluetooth connection
- Air conditioning
- Cruise control
- Front electric windows
- Park assist camera
- Central locking
- Digital radio
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Cracked
Replace



2: Panel Front
Cracked
Replace



3: Panel Front
Cracked
Replace



4: Door nsf
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



6: Qtr Panel nsr
Dented
With Paint Damage



7: B Post ns
Cracked
Replace



8: Qtr Panel osr
Dented
With Paint Damage



9: B Post os
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		