

VEHICLE INSPECTION REPORT

KU71CVR

MERCEDES-BENZ ACTROS 2545

Inspection Vehicle

VAT	Plus VAT		
V5	Present		

Details

Reg. date	11/11/2021	Colour	RED	Gearbox	AUTOMATIC
Year	2021	VIN	W1T96342320537386	Axle Combi	6x2
Mileage	397,035 Km Warranted	Body Style	Tractor Unit	Steering Combi	Mid-Lift
Fuel Type	Diesel	Cab Type	STREAMSPACE CAB	Rear Suspension	Air
			(2.3M, 170MM)		

WARNING LIGHT ON DASH

Tyres

NSF

NSR

OSF

OSR

Spare

Features

Navigation system

• Park assist camera

Photos















