

VEHICLE INSPECTION REPORT

WM21HWB

Ford Transit Custom 300 2.0 ECO BLUE 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Buyer To Apply

Details

Reg. date 04/06/2021

Year 2021

Mileage 40,108 Miles Not Warranted

Fuel Type DIESEL

Colour BLUE

VIN WF0YXXTTGYMP67215

Body Style Panel Van L1

MOT Due 11/06/2026

CAP Clean £10,850.00

CAP Average £9,850.00

CAP Below £8,275.00

Gearbox MANUAL

Gears 6

AD BLUE, SIDE LOADING DOOR

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Front electric windows

Photos





Condition Check



Damage Photos



1: Wing osf
Scratched
UpTo 25mm Thru Paint



2: Screen Front
Chipped
UpTo 10mm



3: Panel Front
Scratched
UpTo 25mm Thru Paint



4: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



5: Door nsf
Scratched
UpTo 25mm Thru Paint



6: Door nsr
Scratched
Over 25mm Thru Paint



7: Qtr Panel nsr
Scratched
UpTo 25mm Thru Paint



8: Lamp nsr
Broken
Replace



9: Door osr
 Scratched
 UpTo 25mm Thru Paint



10: Door Mirror Assy osf
 Scuffed (Unpainted)
 UpTo 100mm



11: Door osf
 Chipped
 Edge Chip

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK