

VEHICLE INSPECTION REPORT

C355297

DON BUR BOX

Inspection

Vehicle

VAT	Plus VAT
V5	N/A

Details

Reg. date	01/01/2013	VIN	SEPBV38GKDL091796	Steering Combi	Front Lift
Year	2013	Body Style	Trailer	Rear Suspension	Air
Mileage	Not Showing	MOT Due	31/05/2026	Rear Doors	Roller
Fuel Type		Brakes	Disc		
Colour	RED	Axle Combi	Tri		

CORROSION BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





