

# VEHICLE INSPECTION REPORT

**C355978**

## DONBUR BOX

### Inspection

### Vehicle

VAT	Plus VAT
V5	N/A

### Details

Reg. date	01/01/2013	VIN	SEPBV38GKDL061844	Steering Combi	Front Lift
Year	2013	Body Style	Trailer	Rear Suspension	Air
Mileage	Not Showing	MOT Due	30/09/2025	Rear Doors	Roller
Fuel Type		Brakes	Disc		
Colour	RED	Axle Combi	Tri		

\*CORROSION\* BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos









