

# VEHICLE INSPECTION REPORT

**FP69ZFA**

## Vauxhall Vivaro 2900 1.5d 100PS Edition

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

nama

GRADE  
2

### Details

Reg. date 31/12/2019

Year 2019

Mileage 48,061 Miles Not Warranted

Fuel Type Diesel

Colour White

VIN VXEVBYHRKL7005057

Body Style Panel Van L1

MOT Due 05/07/2025

CAP Clean £8,550.00

CAP Average £7,475.00

CAP Below £5,975.00

Gearbox MANUAL

TWIN SIDE LOADING DOOR

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Front parking sensor
- Rear parking sensor
- Air conditioning
- Front electric windows


## Photos







## Condition Check



## Damage Photos



1: Bonnet  
Chipped  
Multiple Chips



2: Qtr Panel nsr  
Chipped  
1 To 5



3: Qtr Panel osr  
Scratched  
UpTo 25mm Thru Paint

Interior

Carpet Condition	-	Upholstery Condition	-
Seat Condition	-	Odour	-

EML light illuminated	OK	Service indicator light illuminated	OK
-----------------------	----	-------------------------------------	----