

VEHICLE INSPECTION REPORT

M403PAO

SCANIA R143 TOPLINE

Inspection

Vehicle

VAT	Margin
V5	To Follow

Details

Reg. date	26/08/1994	Colour	WHITE	Gearbox	MANUAL
Year	1994	VIN	04336870	Axle Combi	6x2
Mileage	TBC	Body Style	Tractor Unit		
Fuel Type	Diesel	MOT Due	30/05/2026		

TAG AXLE, ALLOY WHEELS, EMINOX EXHAUSTS

Tyres

NSF
NSR
OSF
OSR
Spare