

VEHICLE INSPECTION REPORT

DEV77S

SCANIA 111

Inspection

Vehicle

VAT	Margin
V5	To Follow

Details

Reg. date	01/05/1978	Colour	RED	Gearbox	MANUAL
Year	1978	VIN	1011555	Axle Combi	4x2
Mileage	1,011,555 Miles Not Warranted	Body Style	Tractor Unit		
Fuel Type	Diesel	Cab Type	SLEEPER CAB		

VERY ORIGINAL LB111. LONG RANGE DIESEL TANKS, SCANIA METAL VISOR, LONGER TRAILER BRAKE HANDLE. DECALS ARE STICKERS. ORIGINALLY FORM THE SCOTTISH BORDERS.

Tyres

NSF
NSR
OSF
OSR
Spare