

VEHICLE INSPECTION REPORT

AK576NJ

SCANIA R113.360

Inspection

Vehicle

VAT	Margin
V5	Buyer To Apply

Details

Reg. date		Colour	WHITE	Gearbox	MANUAL
Year	1991	VIN	XLERA4X2A04311667	Axle Combi	4x2
Mileage	30,682 Km Not Warranted	Body Style	Tractor Unit	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SLEEPER CAB		

ITALIAN REGISTRATION DOCUMENTS AVAILABLE, AIR SUSPENSION ON DRIVE AXLE. ENGINE WAS REBUILT IN 2024, PHOTOGRAPHS & RECEIPTS AVAILABLE.

Tyres

NSF

NSR

OSF

OSR

Spare

Photos





