

VEHICLE INSPECTION REPORT

YH24EZK

Nissan Primastar ACENTA 2.0 DCI 110PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT
V5 Buyer To Apply

Details

Reg. date	17/06/2024	VIN	VNVF4000072032776	CAP Below	£15,000.00
Year	2024	Body Style	Panel Van L2	Gearbox	MANUAL
Mileage	6,843 Miles Warranted	MOT Due	16/06/2027	Gears	6
Fuel Type	DIESEL	CAP Clean	£17,150.00		
Colour	WHITE	CAP Average	£16,500.00		

WARNING LIGHTS ON DASH AD BLUE, SIDE LOADING DOOR, E/MIRRORS

Tyres

NSF

NSR

OSF

OSR


Spare

Features


- Rear parking sensor
- Front electric windows
- Central locking

Photos





Condition Check



Damage Photos




1: Bumper Front Moulding
Scratched (Painted)
UpTo 25mm Thru Paint



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Door Mirror Assy nsf
 Scratched (Painted)
 UpTo 25mm Not Thru Paint



4: Other
 N/A
 N/A



5: Qtr Panel nsr
 Dented
 2 Or Less UpTo 10mm



6: Bumper Rear
 Scratched
 Up To 25mm Not Thru Paint



7: Qtr Panel osr
 Dented
 2 Or Less UpTo 10mm



8: Door Mirror Assy osf
 Scratched (Painted)
 UpTo 25mm Not Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	Fault	Service indicator light illuminated	Fault