

# VEHICLE INSPECTION REPORT

**PJ71NLG**

## Fiat Doblo CARGO 16V 1.6 MULTIJET

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 30/12/2021

Year 2021

Mileage 70,231 Miles  
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V67266

Body Style Dropside L2

MOT Due 02/04/2026

CAP Clean £7,050.00

CAP Average £6,400.00

CAP Below £5,375.00

Gearbox MANUAL

Gears 5

AD-BLUE

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Bumper Front Moulding  
Missing  
Replace



2: Bonnet  
Chipped  
Multiple Chips





3: Roof  
Dented  
Over 30mm



4: Door Moulding nsf  
Broken  
Replace



5: Door Mirror Assy osf  
Broken  
Replace



6: Screen Front  
Cracked  
Replace



7: Seat Base Cover nsf  
Soiled  
Heavy

## Interior

<b>Carpet Condition</b>	OK	<b>Upholstery Condition</b>	OK
<b>Seat Condition</b>	Poor	<b>Odour</b>	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		