

VEHICLE INSPECTION REPORT

SA71ZND

FIAT DOBLO CARGO 16V 1.6 MULTIJET

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/12/2021

Year 2021

Mileage 57,632 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V30027

Body Style Dropside L2

MOT Due 07/12/2025

CAP Clean £7,525.00

CAP Average £6,850.00

CAP Below £5,725.00

Gearbox MANUAL

Gears 5

AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Passenger airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Carpets Front
Holed
Over 3mm



2: Seat Back Cover osf
Torn
Over 3mm



3: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		