

VEHICLE INSPECTION REPORT

SA71KKL

FIAT DOBLO CARGO 16V 1.6 MULTIJET

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/11/2021

Year 2021

Mileage 92,380 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V25572

Body Style Dropside L2

MOT Due 07/11/2025

CAP Clean £6,200.00

CAP Average £5,625.00

CAP Below £4,725.00

Gearbox MANUAL

Gears 5

WARNING LIGHT ON DASH AD-BLUE

Tyres

NSF

NSR

OSF

OSR



Spare

Features

- Rear parking sensor
- Front electric windows
- Central locking


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Broken
Replace



3: Bumper Front Moulding
Missing
Replace



4: Door Mirror Assy nsf
Broken
Replace



5: Door nsf
Scratched
Over 25mm Thru Paint



6: Fuel Flap
Missing
Replace



7: B Post os
Cracked
Replace



8: Door osf
Dented
With Paint Damage



9: Door Mirror Assy osf
Broken
Replace



10: Wing osf
Scratched
Over 25mm Not Thru Paint



11: Carpets Front
Holed
Over 3mm



12: Seat Base Cover osf
Torn
Over 3mm



13: Seat Base Cover nsf
Soiled
Heavy



14: Dash Warning Lights
Displayed
No Action



15: Fascia Panel
Missing
Replace

Interior

Carpet Condition		Upholstery Condition	
Seat Condition		Odour	
Engine Runs		No Excessive Smoking	
EML light illuminated		DPF light illuminated	
ABS light illuminated			