

VEHICLE INSPECTION REPORT

SJ71HSE

FIAT DOBLO CARGO 16V 1.6 MULTIJET

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 19/10/2021

Year 2021

Mileage 84,801 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V18276

Body Style Dropside L2

MOT Due 18/10/2025

CAP Clean £6,450.00

CAP Average £5,875.00

CAP Below £4,925.00

Gearbox MANUAL

Gears 5

AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/CD
- Central locking
- Front electric windows
- Cloth seat trim
- Drivers airbag
- Passenger airbag

Photos





Condition Check



Damage Photos



1: Bumper Front Moulding
Missing
Replace



2: Bonnet
Chipped
Multiple Chips




3: B Post ns
 Scratched
 Over 25mm Not Thru Paint



4: Carpets Front
 Holed
 Over 3mm



5: Seat Base Cover osf
 Soiled
 Heavy



6: Seat Base Cover nsf
 Soiled
 Heavy

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		