

VEHICLE INSPECTION REPORT

VDZ141

SCANIA 141

Imported
Inspection

Vehicle	
VAT	Margin
V5	To Follow

Details

Reg. date	01/01/1980	Colour	ORANGE	Gearbox	MANUAL
Year	1980	VIN	4215679	Axle Combi	4x2
Mileage	TBC	Body Style	Tractor Unit		
Fuel Type	Diesel	Cab Type	SLEEPER CAB		

LEFT HAND DRIVE

Tyres
NSF
NSR
OSF
OSR
Spare

Photos





