

# VEHICLE INSPECTION REPORT

**SF16CMW**

## VAUXHALL MOVANO 3500 2.3 CDTI ECOFLEX 136PS

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	18/07/2016	Body Style	Tipper Double Cab	Gearbox	MANUAL
Year	2016	Keys	2	Gears	6
Mileage	63,218 Miles Warranted	MOT Due	29/07/2026	Doors	4
Fuel Type	Diesel	CAP Clean	£5,450.00	Axle Combi	4x2
Colour	WHITE	CAP Average	£4,550.00	Rear Suspension	Steel
VIN	W0LMSP4Y2GB107233	CAP Below	£3,375.00		

### Tyres

NSF

NSR

OSF


OSR

Spare


## Features

- Park assist camera
- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking


## Photos







## Condition Check



## Damage Photos



1: Door osf  
Chipped  
Edge Chip



2: Sill os  
Rusted  
Over 5mm





3: Wing osf  
Dented  
With Paint Damage



4: Wing osf  
Scratched  
Over 25mm Thru Paint



5: Bonnet  
Scratched  
Over 25mm Thru Paint



6: Bonnet  
Rusted  
Over 5mm



7: Wing nsf  
Dented  
With Paint Damage



8: Sill ns  
Scratched  
Over 25mm Thru Paint



9: Qtr Panel Moulding ns  
Broken  
Replace



10: Door nsf  
Chipped  
Edge Chip



11: Door nsr  
Chipped  
Edge Chip



12: Qtr Panel nsr  
Rusted  
Over 5mm



13: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



14: Bumper Rear  
Dented  
With Paint Damage





15: Qtr Panel osr  
Scratched  
Over 25mm Thru Paint



16: Qtr Panel osr  
Rusted  
Over 5mm

**Interior**

<b>Carpet Condition</b>	Average
<b>Seat Condition</b>	Poor

<b>Upholstery Condition</b>	Poor
<b>Odour</b>	No