

# VEHICLE INSPECTION REPORT

**SJ67LFR**

## Iveco Daily 35-140 2.3 3450 WB

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date 02/10/2017

Year 2017

Mileage 66,092 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFCD35A605177653

Body Style Tipper Double Cab

Keys 1

MOT Due 13/02/2026

CAP Clean £8,925.00

CAP Average £7,575.00

CAP Below £5,750.00

Gearbox AUTOMATIC

Gears 6

Doors 2

Steering Combi Standard Axle

Rear Suspension Steel

### Tyres

NSF

NSR

OSF

OSR

Spare

## Features

- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Bonnet  
Dented  
Over 30mm





3: Wing osf  
Dented  
Over 30mm



4: Door osf  
Dented  
With Paint Damage



5: Door Mirror Assy osf  
Broken  
Replace



6: Qtr Panel osr  
Dented  
Over 30mm



7: Tailgate  
Dented  
With Paint Damage



8: Qtr Panel nsr  
Dented  
With Paint Damage

## Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK	
Parking Brake	OK		No Excessive Smoking	OK	
EML light illuminated	OK		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	
Windows	OK		Radio	OK	
			Steering	OK	