

VEHICLE INSPECTION REPORT

SJ67LFO

Iveco Daily 35-140 2.3 3750 WB

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 02/10/2017

Year 2017

Mileage 34,422 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFCD35A105177110

Body Style Tipper Double Cab

Keys 1

MOT Due Expired

CAP Clean £10,600.00

CAP Average £9,000.00

CAP Below £6,850.00

Gearbox MANUAL

Gears 6

Doors 4

Steering Combi Standard Axle

Rear Suspension Steel

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim

Photos





Condition Check



Damage Photos



1: Seat Base Cover osf
Torn
Over 3mm



2: Bonnet
Dented
Over 30mm



3: Door nsr
Dented
Over 30mm



4: Qtr Panel osr
Dented
With Paint Damage



5: Tailgate
Rusted
Over 5mm



6: Qtr Panel nsr
Dented
Over 30mm



7: Door nsf
Dented
With Paint Damage



8: Wing nsf
Dented
With Paint Damage

Interior

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		No
Engine Runs		OK	Gearbox 1st and Reverse Test		OK
Brakes		OK	Clutch Slip Test from Static		OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)		OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illuminated		OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illuminated		OK
Windows		OK	Radio		OK
			Steering		OK