

# VEHICLE INSPECTION REPORT

**PJ70TOA**

## Daf CF 370

### Inspection

Serious Damage? No

### Vehicle

VAT Plus VAT

V5 Present

### Details

Reg. date	05/01/2021	Body Style	Box Van	Gearbox	AUTOMATIC
Year	2021	MOT Due	31/03/2026	Axle Combi	4x2
Mileage	245,409 Km Warranted	CAP Clean	£1,460.00	Rear Suspension	Steel
Fuel Type	DIESEL	CAP Average	£14,100.00	Rear Doors	Barn
Colour	WHITE	CAP Below	£12,400.00		
VIN	XLRAEM4100G320092	Cab Type	SPACE CAB		

\*WARNING LIGHTS ON DASH\* CARPET TUG CARPET WINCH, SIDE DOORS

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4


## Features

- Air conditioning


## Photos







## Condition Check



## Damage Photos



1: Wing osf  
Scratched  
Over 25mm Not Thru Paint



2: Bumper Front Moulding  
Scratched (Painted)  
UpTo 25mm Thru Paint





3: Wing nsf  
 Scratched  
 UpTo 25mm Not Thru Paint



4: Bumper Front Moulding  
 Scratched (Painted)  
 UpTo 25mm Thru Paint



5: Other  
 N/A  
 N/A



6: Qtr Panel nsr  
 Cracked  
 Replace



7: Other  
 N/A  
 N/A



8: Seat Base Cover osf  
 Holed  
 Over 3mm



9: Other  
N/A  
N/A



10: Other  
N/A  
N/A



11: Other  
N/A  
N/A

**Interior**

Carpet Condition		Average	Upholstery Condition		Average
Seat Condition		Average	Odour		-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK	
Brakes	OK		Clutch Slip Test from Static	OK	
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK	
			No Excessive Smoking	OK	
EML light illuminated	Fault		Oil warning light illuminated	OK	
Airbag light illuminated	OK		DPF light illuminated	OK	
ABS light illuminated	OK		Service indicator light illuminated	OK	