

VEHICLE INSPECTION REPORT

PJ70DNX

Daf CF 370

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	26/11/2020	Body Style	Box Van	Gearbox	AUTOMATIC
Year	2020	MOT Due	30/04/2026	Axle Combi	4x2
Mileage	381,992 Km Warranted	CAP Clean	£14,250.00	Rear Suspension	Air
Fuel Type	Diesel	CAP Average	£13,500.00	Rear Doors	Barn
Colour	WHITE	CAP Below	£11,600.00		
VIN	XLRAEM4100G319227	Cab Type	SPACE CAB		

WARNING LIGHT ON DASH CARPET LIFT

Tyres




NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Front parking sensor
- Radio/CD
- Air conditioning
- Front electric windows
- Central locking
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Other
N/A
N/A



2: Bumper Front
Scratched
UpTo 25mm Not Thru Paint



3: Door nsf
Dented
Hail - Severe

4: Wing nsf
Cracked
Replace



5: Other
N/A
N/A

6: Other
N/A
N/A

Interior

Carpet Condition		Average		Upholstery Condition		Average	
Seat Condition		Average		Odour		-	
Engine Runs	OK			Gearbox 1st and Reverse Test	OK		
Brakes	OK			Clutch Slip Test from Static	OK		
Turbo Boosting	OK			Gearbox Static Gear Selection (engine running)	OK		
Parking Brake	OK			No Excessive Smoking	OK		
EML light illuminated	OK			Oil warning light illuminated	OK		
Airbag light illuminated	OK			DPF light illuminated	Fault		
ABS light illuminated	OK			Service indicator light illuminated	OK		

Roof / sunroof	OK	Radio	OK
Windows	OK	Steering	OK