

VEHICLE INSPECTION REPORT

KU18DYV

MERCEDES-BENZ ANTOS 2545

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Reg. date	04/05/2018	VIN	WDB9630202012321	Axle Combi	6x2
Year	2018	Body Style	Fridge Box	Steering Combi	Rear-Lift Steer
Mileage	487,888 Km Warranted	MOT Due	Expired	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	DAY CAB	Rear Doors	Barn
Colour	WHITE	Gearbox	AUTOMATIC	Tail Lift	Column

WARNING LIGHT ON DASH, MOT INCORRECTLY RECORDED IN MILES/KM, SMOKING FRIDGE BLOCK UNIT, STANBY BY PLUG, AD-BLUE, TWIN EVAP SEPERATOR, GARDNER DENVER HYDRAPACK

Tyres

NSF
NSR
OSF
OSR
Spare

Features

- Park assist camera
- Digital radio
- Air conditioning

Photos





