

VEHICLE INSPECTION REPORT

HV09GUC

MERCEDES-BENZ ACTROS

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Reg. date	10/08/2009	Colour	YELLOW	Gearbox	MANUAL
Year	2009	VIN	WDB9302052L351400	Axle Combi	6x2
Mileage	340,621 Km Not Warranted	Body Style	Vacuum Tanker	Rear Suspension	Air
Fuel Type	Diesel	Cab Type	SLEEPER CAB		

GULLY ATTACHMENT, REAR HOSE ASSEMBLY, AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features

- Digital radio

Photos





