

VEHICLE INSPECTION REPORT

PJ67MGE

Daf CF 440

Non Runner

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 28/11/2017

Year 2017

Mileage 1,147,984 Km
Warranted

Fuel Type Diesel

Colour RED

VIN XLRTGM4100G184895

Body Style Tractor Unit

Service history Yes

Service documents Printout

MOT Due 31/05/2026

Cab Type SLEEPER CAB

Gearbox AUTOMATIC

Axle Combi 6x2

Steering Combi Mid-Lift Steer

Rear Suspension Air

NON RUNNER - TURNS OVER, DOESNT START, HALF SHIFT REMOVED

Tyres


NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Manual sunroof
- Cloth seat trim
- Park assist camera
- Air conditioning
- Auxiliary input socket
- Front electric windows
- Digital radio
- Central locking


Photos







Condition Check



Damage Photos



1: Front TowEye Cvr
Missing
Replace



2: Tailgate Trim Panel
Scuffed (Unpainted)
Over 100mm



3: Door osf
Scratched
Over 25mm Thru Paint



4: Door osf
Chipped
Multiple Chips

Interior

Carpet Condition	Average	Upholstery Condition	Average
Seat Condition	Average	Odour	-
Engine Runs	Fault		
Roof / sunroof	OK	Radio	OK
Windows	OK		