

VEHICLE INSPECTION REPORT

YH17VUY

Ford Ranger XL 2.2 TDCi 150PS

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	To Follow
5			

Details

Fuel Type	Diesel				
	Warranted	Keys	2	Axle Combi	4x4
Mileage	173,505 Miles	Body Style	Pickup Single Cab	Gears	6
Year	2017	VIN	6FPGXXMJ2GGS26898	Gearbox	MANUAL
Reg. date	02/06/2017	Colour	WHITE	MOT Due	25/02/2026

COLLECTED AS NON RUNNER - HEAVY CORROSION

Tyres			
Tyres NSF			
NSR			
OSF			
OSR			
Spare			

Features

- Bluetooth connection
- Air conditioning
- Central locking
- · Cruise control
- · Front electric windows · Cloth seat trim
- Park assist camera
- Drivers airbag
- Radio/CD
- Passenger airbag

Photos
















Condition Check



Damage Photos







2: Bonnet Dented Over 30mm



3: Wing osf Rusted Over 5mm



4: Door osf Dented Over 30mm



5: Qtr Panel osr Dented Over 30mm



6: Tailgate Dented With Paint Damage



7: Qtr Panel nsr Rusted Over 5mm



8: Door nsf Dented Over 30mm



9: Wing nsf Rusted Over 5mm

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Average Odour No	
Engine Runs		OK	Gearbox 1st and Reverse Test	OK
Brakes		OK	Clutch Slip Test from Static	OK
Turbo Boosting		OK	Gearbox Static Gear Selection (engine running)	OK
Parking Brake		OK	No Excessive Smoking	OK
EML light illuminated		OK	Oil warning light illuminated	OK
Airbag light illuminated	(OK	DPF light illuminated	OK
ABS light illuminated		OK	Service indicator light illuminated	OK
Windows		OK	Radio	ОК
			Steering	OK