

VEHICLE INSPECTION REPORT

MK69LZO

Iveco Daily 35-140 2.3 3520WB

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 15/11/2019

Year 2019

Mileage 145,540 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFCG35A505325668

Body Style Panel Van

MOT Due 11/08/2026

CAP Clean £4,150.00

CAP Average £3,650.00

CAP Below £2,925.00

Gearbox AUTOMATIC

Gears 6

AD-BLUE, SIDE LOAD DOOR, E/ MIRRORS,VEHICLE FULLY WRAPPED (ORIGINAL COLOUR WHITE)

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Bluetooth connection
- Front electric windows
- Cloth seat trim
- Cruise control
- Drivers airbag
- Digital radio
- Passenger airbag
- Air conditioning
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Number Plate Front
Broken
Replace



3: Qtr Panel nsr
Chipped
Multiple Chips



4: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



5: Screen Front
Cracked
Replace



6: Carpets Front
Holed
Over 3mm



7: Door nsf
Chipped
Multiple Chips

Interior

Carpet Condition	Poor	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		