

# VEHICLE INSPECTION REPORT

**C355969**

## DON BUR BOX

### Inspection

### Vehicle

|     |          |
|-----|----------|
| VAT | Plus VAT |
| V5  | N/A      |

### Details

|           |             |            |                   |                 |            |
|-----------|-------------|------------|-------------------|-----------------|------------|
| Reg. date | 01/01/2013  | Colour     | RED               | Axle Combi      | Tri        |
| Year      | 2013        | VIN        | SEPBV38GKDL061835 | Steering Combi  | Front Lift |
| Mileage   | Not Showing | Body Style | Trailer           | Rear Suspension | Air        |
| Fuel Type |             | Brakes     | Disc              | Rear Doors      | Roller     |

\*CORROSION\* BPW AXLES, RAISE & LOWER VALVE, FERRY LASHING RINGS

### Tyres

NSF

NSR

OSF

OSR

Spare

### Photos





