

VEHICLE INSPECTION REPORT

FV66VBL

TOYOTA AYGO 1.0 VVT-I X-PRESSION

Cat: N

Inspection Vehicle

| VAT | Margin | |
|-----|----------------|--|
| V5 | Buyer To Apply | |

Details

| Gearbox | MANUAL |
|---------|--------|
| Gears | 5 |
| Doors | 5 |
| | , |
| | |
| (| |

Category N Insurance Loss. No Structural Damage and Repairable - Insurer Decided Not to Repair.

| T | У | r | е | S |
|---|---|---|---|---|
|---|---|---|---|---|

NSF

NSR

OSF

OSR Spare

Features

- Park assist camera
- · Front electric windows
- Body coloured bumpers
- Rear electric windows
- · Electric door mirrors
- Alloy wheels
- Air conditioning
- Spare wheel

Photos















