

VEHICLE INSPECTION REPORT

SA58HFW

Ford Transit Connect TDCI T230 L LWB P/V 90

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	To Follow		
Details					
Reg. date	07/11/2008	VIN	WF0UXXTTPU7P51626	Gears	5
Year	2008	Body Style	Panel Van LWB	Doors	2
Mileage	43,684 Miles Warranted	Keys	1	Steering Combi	Standard Axle
		MOT Due	27/12/2025	Rear Suspension	Steel
Fuel Type	Diesel	Gearbox	MANUAL		
Colour	WHITE				
Tyres NSF					
NSR					
OSF					
OSR					
Spare	_	· · · · · · · · · · · · · · · · · · ·		· · · · · · · · · · · · · · · · · · ·	_

Features

- Radio/CD
 Cloth seat trim
- Front electric windows
- Drivers airbag
- Central locking

Photos





























Condition Check



Damage Photos



1: Sill os Rusted Over 5mm



2: Bonnet Chipped 1 To 5



3: Wing osf Dented Over 30mm



4: Door osf Dented Over 30mm



5: Qtr Panel osr Dented Over 30mm



6: Tailgate Dented Over 30mm



7: Qtr Panel nsr Dented Over 30mm



8: Sill ns Rusted Over 5mm



9: Door nsf Dented Over 30mm

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		OK	Gearbox 1st and Revers	se Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Turbo Boosting		OK	Gearbox Static Gear Se	lection (engine running)	OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ited	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	uminated	OK
Windows		ОК	Radio		OK
			Steering		OK