

VEHICLE INSPECTION REPORT

WV22UVJ

Ford Transit 2.0 EcoBlue 185ps Limited

Inspection		Vehicle			
Serious Damage?	No	VAT	Plus VAT		
		V5	Buyer To Apply		
Details					
Reg. date	23/06/2022	Body Style	Panel Van XLWB	Gears	6
Year	2022	Keys	1	Doors	2
Mileage	52,778 Miles Not Warranted	CAP Clean	£16,300.00	Axle Combi	4x2
		CAP Average	£15,050.00	Steering Combi	Standard Axle
Fuel Type	Diesel	CAP Below	£13,000.00	Rear Suspension	Steel
Colour	GREY	Gearbox	MANUAL	·	
VIN	WF0EXXTTRENY30135			_	

NEAR SIDE MIRROR BROKEN/MISSING

Tyre	S
NSF	

NSR

OSF

OSR

Spare

Features

- Bluetooth connection
- Front electric windows
- Cloth seat trim
- · Rear parking sensor
- Metallic Paint
- Radio/CD
- Drivers airbag
- Air conditioning
- Central locking

Photos










Condition Check



Damage Photos



1: Bumper Front Scratched Over 25mm Not Thru Paint



2: Door osf Dented Over 30mm



3: Flasher Side Repeater os Broken Replace



4: Door Moulding osf Broken Replace



5: Tailgate Dented Over 30mm



6: Door nsr Dented Over 30mm



7: Flasher Side Repeater ns Broken Replace



8: Flasher Side Repeater ns Broken Replace

Interior

Carpet Condition Seat Condition	Average Average		Upholstery Condition Odour	Average No	
Engine Runs		OK	Gearbox 1st and Revers	e Test	OK
Brakes		OK	Clutch Slip Test from Sta	atic	OK
Turbo Boosting		OK	Gearbox Static Gear Sel	ection (engine running)	OK
Parking Brake		OK	No Excessive Smoking		OK
EML light illuminated		OK	Oil warning light illumina	ted	OK
Airbag light illuminated		OK	DPF light illuminated		OK
ABS light illuminated		OK	Service indicator light illu	ıminated	OK
Windows		OK	Radio		OK
			Steering		OK