

VEHICLE INSPECTION REPORT

CN24VBT

Ford Ranger WILDTRAK 2.0 ECOBLUE

Inspection		Vehicle	
Serious Damage?	No	VAT	Plus VAT
		V5	Buyer To Apply

Details					
Reg. date	13/03/2024	Colour	BLACK	CAP Average	£26,900.00
Year	2024	VIN	6FPPXXMJ2PPM31239	CAP Below	£24,200.00
Mileage	28,178 Miles Not Warranted	Body Style	Pickup Double Cab	Gearbox	AUTOMATIC
Fuel Type	Diesel	CAP Clean	£27,950.00	Gears	1

WARNING LIGHT ON DASH AD BLUE, E/MIRRORS, ALLOY WHEELS



Tyres	
NSF	
NSR	
OSF	
OSR	
Spare	

Features


- Front parking sensor
- Air conditioning
- Navigation system
- Front electric windows
- Park assist camera
- Leather seat trim
- Rear parking sensor

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Moulding nsf Wing
Scratched (Painted)
Over 25mm Thru Paint



3: Qtr Panel Arch Extension ns
Scratched (Painted)
Over 25mm Thru Paint



4: Qtr Panel Arch Extension os
Scratched (Painted)
UpTo 25mm Thru Paint



5: Door osf
Chipped
Over 5mm

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK	Service indicator light illuminated	OK