

# VEHICLE INSPECTION REPORT

**FD68OYX**

## Daf XF 480

### Inspection

Conditions	Outdoors - Good light
Serious Damage?	No

### Vehicle

VAT	Plus VAT
V5	To Follow

### Details


Reg. date	21/02/2019	VIN	XLRTGH4300G250007	Gearbox	AUTOMATIC
Year	2019	Body Style	Tractor Unit	Axle Combi	6x2
Mileage	606,483 Km Not Warranted	Keys	1	Rear Suspension	Air
Fuel Type	Diesel	MOT Due	28/02/2026		
Colour	Blue	Cab Type	SPACE CAB		

SPACE CAB, A/C, MID LIFT & STEER, SURROUND CAMERA SYSTEM, SLIDING 5TH WHEEL

### Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

### Photos







This is issued as proof of compliance with the weights and dimensions directive 85/3/EEC

Plate: VTG6A DTp Ref. No. 007062

Vehicle Identification No. XLRTGH4300G250007 Variant

Approval No. DAF/XF 480 FTG Speed Limiter Exempt No

(1) Description of Weights Applicable to vehicle	(2) Weights not to be exceeded in Gt. Britain	(3) EEC Maximum permitted weights (See note 6)	(4) Design Weights (if higher than shown in column 3)	Length	Width
Gross Weight	23700	26000	27000	6310	2550
Gross Weight (See note 7)	44000	40000	50000		
Gross Weight (See note 7)	44000	40000	40000		
Gross Weight (See note 7)	8000	8000	8000		
Gross Weight (See note 7)	17000	17000	17000		
Gross Weight (See note 7)	11000	11000	11000		

a. Coupling centre to vehicle foremost part (See note 6)

b. Coupling centre to vehicle rearmost part (See note 7)

Date of issue

DEPARTMENT FOR TRANSPORT GREAT BRITAIN

Replacement

28

DAF TRUCKS N.V.

ADR4

E4


Type H4GN3

Motor no. A366699

Weight	kg	Weight	kg
027000	kg	027000	kg
044000	kg	050000	kg
060000	kg	1 - 008000	kg
075000	kg	2 - 007500	kg
115000	kg	3 - 011500	kg
019000	kg	4 - 000000	kg
		T - 019000	kg



## Condition Check



## Damage Photos



1: Qtr Panel nsr  
Scratched  
Over 25mm Thru Paint



2: Door Moulding nsf  
Scuffed (Unpainted)  
Over 100mm





3: Bumper Front  
Scratched  
Over 100mm Thru Paint



4: Wing osf  
Chipped  
Multiple Chips



5: Qtr Panel osr  
Rusted  
Over 5mm



6: Unclassified  
Major Parts Missing  
Report Only

**Interior**

**Carpet Condition**      Average  
**Seat Condition**      Average

**Upholstery Condition**      Average  
**Odour**      -

**Mechanical Inspection**

**Important Notice:** Customer must satisfy themselves that the health check is as stated by 5pm day after sale and prior to leaving centre. If vehicle has been delivered we must be notified within two hours of arrival at your dealership.

EML light illuminated      Fault