

VEHICLE INSPECTION REPORT

PE19HLA

FIAT DUCATO 35 2.3 MULTIJET 130PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 20/03/2019

Year 2019

Mileage 161,183 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002K14949

Body Style Dropside

MOT Due 26/03/2026

CAP Clean £3,550.00

CAP Average £3,100.00

CAP Below £2,450.00

Gearbox MANUAL

Gears 6

Tail Lift Column

MOT HISTORY SHOWS 133,848 MILES IN MARCH 2022, POSSIBLE INPUT ERROR AD-BLUE, E/ MIRRORS, TOW BAR

Tyres

NSF

NSR

OSF

OSR


Spare

Features

- Bluetooth connection
- Drivers airbag
- Park assist camera
- Passenger airbag
- Digital radio
- Central locking
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bumper Front
Dented
Over 30% Of Panel



2: Panel Front
Chipped
Multiple Chips



3: Badgedecal Front
Missing
Replace



4: Bonnet
Chipped
Multiple Chips



5: Lamp nsr
Broken
Replace



6: Door Mirror Assy osf
Broken
Replace



7: Wing osf
Scratched
Over 25mm Thru Paint



8: Door Pad osf
Soiled
Heavy



9: Seat Base Cover nsf
Soiled
Heavy



10: Door Pad nsf
Soiled
Heavy

Interior

| Carpet Condition | | Upholstery Condition | |
|-----------------------|----|-----------------------|----|
| Seat Condition | | Odour | |
| OK | | Poor | |
| Poor | | No | |
| Engine Runs | OK | No Excessive Smoking | OK |
| EML light illuminated | OK | DPF light illuminated | OK |
| ABS light illuminated | OK | | |