

VEHICLE INSPECTION REPORT

GVG876K

SCANIA 140

Imported

Inspection

Vehicle

VAT	Plus VAT
V5	To Follow

Details

Reg. date	13/11/1975	Fuel Type	Diesel	Body Style	Recovery
Year	1971	Colour	RED	Gearbox	MANUAL
Mileage	718,627 Km Not Warranted	VIN	456849	Axle Combi	4x2

ORIGINALLY A SVEMPAS RECOVERY TRUCK, BRO EQUIPMENT, TWIN WINCHES (LARGER WINCH NOT WORKING), CORRECT FRONT BUMPER AND DROP WINGS INCLUDED IN THE SALE, FUEL LINES / TANK REQ ATTN., CURRENTLY RUNNING FROM A FUEL CAN IN SIDE LOCKER.

Tyres

NSF
NSR
OSF
OSR
Spare

Photos

