

VEHICLE INSPECTION REPORT

SG68XYD

Fiat Ducato 42 2.3 MULTIJET 180PS

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/11/2018

Year 2018

Mileage 77,843 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA25000002H63986

Body Style Minibus

MOT Due 16/10/2025

Gearbox MANUAL

Tyres

NSF

NSR

OSF

OSR

Spare


Features

- Bluetooth connection
- Front electric windows
- Park assist camera
- Drivers airbag
- Digital radio
- Central locking
- Air conditioning
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
25 to 100mm Thru Paint



3: Qtr Panel osr
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		